




# Sakura Gomon Restoration and Improvement Work

## Progress of Construction

Construction, which began with the procurement and processing of timber, took a total of 31 months to complete, six months longer than originally planned, due in part to COVID-19.



Construction Blueprints (partial)

## Craftsmen's Handiwork

Many craftsmen, including carpenters, tilers, plasterers, and stonemasons, were involved in the construction exercising their knowledge and skills. While using modern tools, such as heavy machinery and power tools, careful handiwork was done with a strong awareness of Edo Period (1603-1867) and the texture (landscape) of the structure. Look for the modern craftsmanship, which can be seen here and there. It has made it possible to restore this historic gate.



Making Roof Tiles



Assemble Wood



Roofing Tiles



Plastering

